

**Duanesburg Central School District
Lead Water Test Results**

Sample Number	Location	Source	Initial Test Date	Parts Per Billion	Initial Condition	30 Second Draw Date	30 Second Draw Result Parts Per Billion	Remediation Plan	Replacement Result	Full Secondary Test Results Date	Secondary Test Date Results per Billion	Result Date	Current Status
1	Booster Club Room -Original Prior to 2017	Counter Sink	9/19/2016	0.48	Passed								Unit Removed Relocation of Room
2	Girls Toilet Room Near 110	Toilet Room Sink	9/19/2016	0.53	Passed								PASSED
3	Girls Toilet Room Near 110	Toilet Room Sink	9/19/2016	0.72	Passed								PASSED
4	Girls Toilet Room Near 110	Toilet Room Sink	9/19/2016	0.55	Passed								PASSED
5	Boys Toilet Room Near 110	Toilet Room Sink	9/19/2016	0.28	Passed								PASSED
6	Boys Toilet Room Near 110	Toilet Room Sink	9/19/2016	0.65	Passed								PASSED
7	Boys Toilet Room Near 110	Toilet Room Sink	9/19/2016	0.38	Passed								PASSED
8	Room 110 - Science Room	Classroom Sink	9/19/2016	13.1	Passed								PASSED
9	Room 110 - Science Room	Classroom Sink	9/19/2016	9.1	Passed								PASSED
10	Room 110 - Science Room	Classroom Sink	9/19/2016	13.3	Passed								PASSED
11	Room 110 - Science Room	Teacher Sink	9/19/2016	14.7	Passed								PASSED
12	Staff Toilet Room	Toilet Room Sink	9/19/2016	1.2	Passed								PASSED
13	Staff Toilet Room	Toilet Room Sink	9/19/2016	0.31	Passed								PASSED
14	Science Prep Room 110A	Counter Sink	9/19/2016	14.4	Passed								PASSED
15	Science Room 111	Counter Sink	9/19/2016	11.9	Passed								PASSED
16	Science Room 111	Classroom Counter Sink	9/19/2016	40.2	Failed	10/13/2016	1.8	Replace Fixture and Valves / POSTED DO NOT DRINK					PASSED
17	Science Room 111	Classroom Counter Sink	9/19/2016	2.3	Passed			POSTED DO NOT DRINK					PASSED
18	Science Room 111	Classroom Counter Sink	9/19/2016	13.5	Passed			POSTED DO NOT DRINK					PASSED
19	Science Room 111	Classroom Counter Sink	9/19/2016	6.9	Passed			POSTED DO NOT DRINK					PASSED
20	Science Room 111	Classroom Counter Sink	9/19/2016	8.3	Passed			POSTED DO NOT DRINK					PASSED
21	Science Room 111	Classroom Counter Sink	9/19/2016	122	Failed	10/13/2016	0.88	Replace Fixture and Valves / Posted DO NOT DRINK					PASSED
22	Science Room 112	Classroom Counter Sink	9/19/2016	2.1	Passed			POSTED DO NOT DRINK					PASSED
23	Science Room 112	Classroom Counter Sink	9/19/2016	1.4	Passed			POSTED DO NOT DRINK					PASSED
24	Science Room 112	Classroom Counter Sink	9/19/2016	0.75	Passed			POSTED DO NOT DRINK					PASSED
25	Hallway Drinking Fountain Near 116	Drinking Fountain	9/19/2016	5.5	Passed								PASSED
26	Hallway Drinking Fountain Near 116	Drinking Fountain	9/19/2016	5.5	Passed								PASSED
27	Boys Toilet Room Locker Room	Toilet Room Sink	9/19/2016	10.9	Passed								PASSED
28	Boys Toilet Room Locker Room	Toilet Room Sink	9/19/2016	3.7	Passed								PASSED
29	Boys Locker Room	Drinking Fountain	9/19/2016	2	Passed								PASSED
30	Referee Office State Police	Toilet Room Sink	9/19/2016	21.6	Failed	10/13/2016	1.1	Replace Fixture and Valves / Posted DO NOT DRINK					PASSED
31	Hallway Drinking Fountain Near 109	Drinking Fountain	9/19/2016	0.5	Passed								PASSED
32	Girls Locker Room	Toilet Room Sink	9/19/2016	2.9	Passed								PASSED
33	Girls Locker Room	Toilet Room Sink	9/19/2016	1.8	Passed								PASSED
34	Girls Locker Room	Toilet Room Sink	9/19/2016	6.9	Passed								PASSED
35	Girls Gang Toilet Room Near Gym	Toilet Room Sink	9/19/2016	0.96	Passed								PASSED
36	Girls Gang Toilet Room Near Gym	Toilet Room Sink	9/19/2016	0.41	Passed								PASSED
37	Girls Gang Toilet Room Near Gym	Toilet Room Sink	9/19/2016	1.6	Passed								PASSED
38	Hallway Drinking Fountain Near Boiler Room	Drinking Fountain	9/19/2016	0.14	Passed								PASSED
39	Science Room 105	Classroom Counter Sink	9/19/2016	16.5	Failed	10/13/2016	0.85						2018 -DO NOT EXIST
40	Science Room 105	Classroom Counter Sink	9/19/2016	15	Passed								2018 -DO NOT EXIST
41	Science Room 105	Classroom Counter Sink	9/19/2016	8.6	Passed								2018 -DO NOT EXIST
42	Science Room 105	Classroom Counter Sink	9/19/2016	11.9	Passed								2018 -DO NOT EXIST
43	Science Room 105	Classroom Counter Sink	9/19/2016	25.4	Failed	10/13/2016	22.4						2018 -DO NOT EXIST
44	Hallway Drinking Fountain Near Room 102	Drinking Fountain	9/19/2016	10.7	Passed								PASSED
45	Kitchen	Pot Filler	9/19/2016	9.3	Passed								PASSED
46	Kitchen	Kitchen Sink	9/19/2016	1.6	Passed								PASSED
47	Kitchen	Kitchen Sink	9/19/2016	3.6	Passed								PASSED
48	Cafeteria	Drinking Fountain	9/19/2016	1.2	Passed								PASSED
49	Family Consumer Science Room 100B	Kitchen Sink	9/19/2016	15.1	Failed	10/13/2016	1.1			2/22/2017	2.7	2/27/2017	PASSED
50	Family Consumer Science Room 100B	Kitchen Sink	9/19/2016	3.2	Passed								PASSED
51	Family Consumer Science Room 100B	Kitchen Sink	9/19/2016	3.5	Passed								PASSED
52	Family Consumer Science Room 100B	Kitchen Sink	9/19/2016	16.8	Failed	10/13/2016	0.26			11/8/2016	2.2	12/5/2016	PASSED
53	Family Consumer Science Room 100B	Kitchen Sink	9/19/2016	5.6	Passed								PASSED

**Duanesburg Central School District
Lead Water Test Results**

Sample Number	Location	Source	Initial Test Date	Parts Per Billion	Initial Condition	30 Second Draw Date	30 Second Draw Result Parts Per Billion	Remediation Plan	Replacement Result	Full Secondary Test Results Date	Secondary Test Date Results per Billion	Result Date	Current Status
54	Nurse Office Sink Original	Office Sink	9/19/2016	2.3	Passed								2018 -DO NOT EXIST
55	Nurse Toilet Room Sink original	Toilet Room Sink	9/19/2016	9.8	Passed								2018 -DO NOT EXIST
56	Staff Toilet Room Mens	Toilet Room Sink	9/19/2016	0.76	Passed								PASSED
57	Staff Toilet Room Women	Toilet Room Sink	9/19/2016	2.5	Passed								PASSED
58	Staff Faculty Room	Break Room Sink	9/19/2016	0.42	Passed								PASSED
59	Staff Toilet Room 3rd Floor	Toilet Room Sink	9/19/2016	0.39	Passed								PASSED
60	Toilet Room Student 3rd Floor	Toilet Room Sink	9/19/2016	0.22	Passed								PASSED
61	Hallway Drinking Fountain 3rd Floor	Drinking Fountain	9/19/2016	0.29	Passed								PASSED
62	Vestibule Sink Near 305	Sink	9/19/2016	0.98	Passed								PASSED
63	Vestibule Sink Near 305	Sink	9/19/2016	0.68	Passed								PASSED
64	Art Room 208	Classroom Sink	9/19/2016	5.9	Passed								PASSED
65	Art Room 208	Classroom Sink	9/19/2016	5.6	Passed								PASSED
66	Toilet Room in Central Office (Mens)	Toilet Room Sink	9/19/2016	2.6	Passed								PASSED
67	Toilet Room in Central Office (Ladies)	Toilet Room Sink	9/19/2016	0.43	Passed								PASSED
68	Central Office Break Room	Break Room Sink	9/19/2016	1	Passed								PASSED
69	Central Office	Outside Hose Connection	9/19/2016	0.12	Passed								PASSED
70	Ballfield Hose Outside 113	Outside Hose Connection	9/19/2016	<0.10	Passed								PASSED
71	Room 106	Classroom Wash Sink	9/19/2016	20.4	Failed	10/13/2016	20.4	Removed Sink					SINK REMOVED
72	Room 106	Classroom Wash Sink	9/19/2016	1.4	Passed								PASSED
73	Boiler Room	Hose Connection	9/19/2016	16.6	Passed								PASSED
74	Technology Room 102	Wash Basin Sink	9/19/2016	5.7	Passed								PASSED
75	Technology Room 102	Wash Sink	9/19/2016	5.4	Passed								PASSED
76	Old Boiler Room	Water Inlet near Village of Delanson	9/19/2016	408	Failed	10/13/2016	4.8	Capped					OUT OF SERVICE
77	Hallway near Nurse Office	Drinking Fountain	9/19/2016	0.44	Passed								PASSED
78	Toilet Room Sink (Girls)	Toilet Room Sink	9/19/2016	0.45	Passed								PASSED
79	Toilet Room Sink (Boys)	Toilet Room Sink	9/19/2016	0.59	Passed								PASSED
80	Science Room 202	Utility Sink	9/19/2016	2.1	Passed								PASSED
81	Library Office Room 207	Office Sink	9/19/2016	14.1	Passed								PASSED
82	Library Copy Room 207	Sink	9/19/2016	4.1	Passed								PASSED
83	Third Floor Mop Closet	Mop Sink	9/19/2016	4.2	Passed								PASSED
84	Booster Club Room	Hose Connection	9/19/2016	13.9	Passed								PASSED
85	Girls Locker Room	Girls Shower	9/19/2016	116	Failed				POSTED NON-POTABLE WATER				FAILED
86	Girls Locker Room	Girls Shower	9/19/2016	102	Failed				POSTED NON-POTABLE WATER				FAILED
87	Girls Locker Room	Girls Shower	9/19/2016	50.3	Failed				POSTED NON-POTABLE WATER				FAILED
88	Girls Locker Room	Girls Shower	9/19/2016	55.1	Failed				POSTED NON-POTABLE WATER				FAILED
89	Girls Locker Room	Girls Shower	9/19/2016	34.9	Failed				POSTED NON-POTABLE WATER				FAILED
90	Girls Locker Room	Girls Shower	9/19/2016	52.2	Failed				POSTED NON-POTABLE WATER				FAILED
91	Boys Locker Room	Boys Shower	9/19/2016	41.8	Failed				POSTED NON-POTABLE WATER				FAILED
92	Boys Locker Room	Boys Shower	9/19/2016	44.8	Failed				POSTED NON-POTABLE WATER				FAILED
93	Boys Locker Room	Boys Shower	9/19/2016	48.9	Failed				POSTED NON-POTABLE WATER				FAILED
94	Boys Locker Room	Boys Shower	9/19/2016	84.4	Failed				POSTED NON-POTABLE WATER				FAILED
95	Boys Locker Room	Boys Shower	9/19/2016	26.3	Failed				POSTED NON-POTABLE WATER				FAILED
96	Boys Locker Room	Boys Shower	9/19/2016	45.1	Failed				POSTED NON-POTABLE WATER				FAILED
97	Boys Locker Room	Boys Shower	9/19/2016	188	Failed				POSTED NON-POTABLE WATER				FAILED
98	Boys Locker Room	Boys Shower	9/19/2016	37.2	Failed				POSTED NON-POTABLE WATER				FAILED
99	Boys Locker Room	Boys Shower	9/19/2016	24	Failed				POSTED NON-POTABLE WATER				FAILED
100	Boys Locker Room	Boys Shower	9/19/2016	9.3	Passed								PASSED
101	Kitchen	Kitchen Kettle	9/19/2016	1.4	Passed								PASSED
102	Outside maintenance Garage	Hose Connection	9/19/2016	1.8	Passed								PASSED
103	Booster Club Room	Ice Machine	9/19/2016	0.23	Passed								PASSED
1805621	Auditorium Girls Gang Toilet Room	Sink 104	7/25/2018	< 0.0005	Passed								PASSED
1805622	Auditorium Girls Gang Toilet Room	Sink 105	7/25/2018	< 0.0005	Passed								PASSED
1805623	Auditorium Girls Gang Toilet Room	Sink 106	7/25/2018	< 0.0005	Passed								PASSED

**Duanesburg Central School District
Lead Water Test Results**

Sample Number	Location	Source	Initial Test Date	Parts Per Billion	Initial Condition	30 Second Draw Date	30 Second Draw Result Parts Per Billion	Remediation Plan	Replacement Result	Full Secondary Test Results Date	Secondary Test Date Results per Billion	Result Date	Current Status
1805624	Auditorium Girls Gang Toilet Room	Sink 107	7/25/2018	< 0.0005	Passed								PASSED
1805625	Auditorium Girls Gang Toilet Room	Sink 108	7/25/2018	< 0.0005	Passed								PASSED
1805626	Auditorium Boys Gang Toilet Room	Sink 109	7/25/2018	< 0.0005	Passed								PASSED
1805627	Auditorium Boys Gang Toilet Room	Sink 110	7/25/2018	< 0.0005	Passed								PASSED
1805628	Auditorium Boys Gang Toilet Room	Sink 111	7/25/2018	< 0.0005	Passed								PASSED
1805629	Auditorium Boys Gang Toilet Room	Sink 112	7/25/2018	< 0.0005	Passed								PASSED
1805630	Auditorium Boys Gang Toilet Room	Sink 113	7/25/2018	< 0.0005	Passed								PASSED
1805631	Auditorium Water Fountain	Fountain 114A	7/25/2018	< 0.0005	Passed								PASSED
1805632	Auditorium Water Fountain	Fountain 114B	7/25/2018	< 0.0005	Passed								PASSED
1805633	Nurses Exam Room	Sink 115	7/25/2018	< 0.0005	Passed								PASSED
1805634	Nurses Exam Room	Sink 116	7/25/2018	< 0.0005	Passed								PASSED
1805635	Nurses Exam Room	Sink 117	7/25/2018	< 0.0005	Passed								PASSED
1805636	Booster Club Room	Sink 118	7/25/2018	< 0.0005	Passed								PASSED
1805637	Booster Club Room	Ice Machine Source 103	7/25/2018	0.0012	Passed								PASSED
1805638	Science Room #113	Lab Sink 119	7/25/2018	< 0.0005	Passed								PASSED
1805639	Gymnasium	Water Fountain Girls Side #038	7/25/2018	< 0.0005	Passed								PASSED